



Field Bulletin

- Interface Card Connector
- SC66/83 XX X

Bulletin #: FG07006

Date: June 07, 2006

Subject: Contact stabilization feature added to SC Interface Board Connector.

Units Affected : SCX66/88 XX X

Summary:

This documents detail changes to the interface board connector PN: 252079045.

Details:

MEI has made a design change to the SC interface PCB connector. The connector part number has been changed from 252074039 to 252079045. This change does not effect the part number of the Interface PCB PN: 252016090P1. Classified as a product enhancement, the change increases connection stability between the interface board and the connector by adding a raised dimple to the connector contacts. See figure below for details.

Part Number:

252079045 Connector, Interface Board SC

Affected Model(s)/PN:

252074039 Connector, Interface Board SC


Questions should be directed to MEI Technical Support at 1-800-345-8172

Date of Effectiveness:

See configuration chart below. The configuration code is the 5th and 6th digit of the units serial number.

Product	Part Number	Configuration Code	Week/YR
SC6602	62542590	14	425
SC6604	252005016	16	425
SC6607	252004020	16	425
SC6607R	252007032	16	425
SCL6601	252208008	17	425
SCL6607	252200002	17	425
SCL 6607	252009016	17	425
SCL6607R	252202006	09	425
SCL6607RL	252209011	09	425
SC8302	62545190	08	425
SC8304	252001030	09	425
SC8307	252009031	09	425
SC8307R	252005033	09	425
SCL8301	252206009	10	425
SCL8307	252204005	10	425
SCL8307R	252200007	10	425
SCL8307RL	252201010	10	425

Questions should be directed to MEI Technical Support at 1-800-345-8172



bottom view

PN: 252069045 G1

Questions should be directed to MEI Technical Support at 1-800-345-8172